


Featured Products Bulletin

RESISTOR NETWORKS


Pin One Marking Change

Riverside, California - May 16, 2012 - Effective with manufacturing date code 1219, the mark designating pin one on components for Bourns® [Model 41xx](#), [43xx](#), [44xx](#), and [48xx resistor networks](#) will change from a laser marked square to a laser marked round dot.

This is a running change and there may be packaging with either of the two marks in the same shipment. There is no change to form, fit or function.



Before



After

Please contact your local [Bourns Representative](#) or [Bourns Customer Service](#) for further information.