



PRODUCT OBSOLESCENCE MEMO

PRECISION POTENTIOMETERS

Bourns® Model 3751H-436-102L Precision Potentiometer to be Discontinued

Riverside, California – July 30, 2020 – In accordance with our ongoing product lifecycle management procedure and due to low volume production, Bourns will transfer the Model 3751H-436-102L Precision Potentiometer to an End of Product Life status on September 29, 2020.

A recommended replacement product is available – Model 3751H-1-102L. The replacement device is pin-to-pin compatible and generally functionally equivalent, but with a difference in storage temperature range as follows:

- 3751H-436-102L: -65 °C to +105 °C
- 3751H-1-102L: -55 °C to +105 °C

Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement product and your application requirements. The affected part number and the recommended replacement part number appears below.

Obsolete Part Number	Recommended Replacement Part Number
3751H-436-102L	3751H-1-102L

Customers may continue to purchase this discontinued product during the End of Product Life transition period between now and September 29, 2020. Discontinued products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Orders for this discontinued product during this End of Product Life transition period will be considered noncancellable and non-refundable.

Please plan for the following deadlines:

Last Time Buy Date: **September 29, 2020**
Last Time Ship Date: **December 29, 2020**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

SC2040